



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
January 19, 2007

Supervisor DRH

**Mine Name:** Utelite Mine  
**Operator Name:** Utelite Corporation

**Permit number:** M0430004  
**Inspection Date:** June 13, 2006  
**Time:** 3:00 pm

**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** Carsten Mortensen  
**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Routine inspection while in the area.

**Inspection Summary:**

This inspection centered on the amended portion of the site. Topsoil has been salvaged and stockpiled. The stockpile was seeded and a protective vegetation cover has established. The disturbed area (permitted) boundary of this area was marked (fencing or posts) All disturbance was within the marked area. There were no signs that runoff was leaving the area.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**

This site is in compliance at this time. Continue to monitor this site when in the area.

**Inspector's Signature**   *LK*  

LK:pb

**Date:** January 19, 2007

O:\M043-Summit\M0430004-UteliteMine\Inspections\Insp-06132006.doc